


MODEL: FSX20-184 forging spring mounts









KEEPER BAR TYPE ARRANGEMENTS







The slope of the concrete surface under the isolator must not exceed 0.07 inches/foot (5.8 mm/meter). Uneven loading of the coil springs occurs when the isolator is tilted, or twisted, causing excessive stress. Self-leveling grout or a steel plate covering the pit bottom is recommended if the supporting surface exceeds the tolerances shown above.



NOTE: Isolator data subject to change without notice.



